

Jeep Aluminum TrailChaser® Bumper Kits & Components

| Location / Make / Model | Years | Kit# | Center# | Corner# | Corner Lights | Guard# | Guard Style | Fender Flare# | Footnotes | | |
|-------------------------------|---------|------------------|---------|---------|------------------------------|---------|-------------|---------------|-----------|----|----|
| Front Aluminum Bumpers | | | | | | | | | | | |
| Jeep Gladiator JT | 20 - 20 | 2082075 | 2081004 | 2081205 | Included | -- | -- | -- | -- | | |
| | | 2082094 | 2081004 | 2081205 | Included | 2081255 | Round | -- | -- | | |
| | | 2082095 | 2081004 | 2081205 | Included | 2081101 | Angular | -- | -- | | |
| | | 2082074 | 2081004 | 2081207 | Not compatible | -- | -- | -- | -- | | |
| | | 2082092 | 2081004 | 2081207 | Not compatible | 2081255 | Round | -- | -- | | |
| | | 2082093 | 2081004 | 2081207 | Not compatible | 2081101 | Angular | -- | -- | | |
| Jeep Wrangler JL | 18 - 20 | 2082076 | 2081004 | 2081209 | Accepts OE turn signal lamps | -- | -- | -- | -- | | |
| | | 2082098 | 2081004 | 2081209 | Accepts OE turn signal lamps | 2081255 | Round | -- | -- | | |
| | | 2082099 | 2081004 | 2081209 | Accepts OE turn signal lamps | 2081101 | Angular | -- | -- | | |
| | | 2082077 | 2081004 | 2081209 | Accepts OE turn signal lamps | -- | -- | 1500203 | 1 | | |
| | | 2082096 | 2081004 | 2081209 | Accepts OE turn signal lamps | 2081255 | Round | 1500203 | 1 | | |
| | | 2082097 | 2081004 | 2081209 | Accepts OE turn signal lamps | 2081101 | Angular | 1500203 | 1 | | |
| | | 2082075 | 2081004 | 2081205 | Included | -- | -- | -- | -- | | |
| | | 2082094 | 2081004 | 2081205 | Included | 2081255 | Round | -- | -- | | |
| | | 2082095 | 2081004 | 2081205 | Included | 2081101 | Angular | -- | -- | | |
| | | 2082074 | 2081004 | 2081207 | Not compatible | -- | -- | -- | -- | | |
| | | 2082092 | 2081004 | 2081207 | Not compatible | 2081255 | Round | -- | -- | | |
| | | 2082093 | 2081004 | 2081207 | Not compatible | 2081101 | Angular | -- | -- | | |
| | | Jeep Wrangler JK | 07 - 18 | 2082046 | 2081001 | 2081205 | Included | 2081101 | Angular | -- | -- |
| | | | | 2082058 | 2081001 | 2081205 | Included | 2081255 | Round | -- | -- |
| 2082044 | 2081001 | | | 2081205 | Included | -- | -- | -- | -- | | |
| 2082055 | 2081001 | | | 2081207 | Not compatible | 2081101 | Angular | -- | -- | | |
| 2082054 | 2081001 | | | 2081207 | Not compatible | 2081255 | Round | -- | -- | | |
| 2082052 | 2081001 | | | 2081207 | Not compatible | -- | -- | -- | -- | | |
| Rear Aluminum Bumpers | | | | | | | | | | | |
| Wrangler JL | 18 - 20 | 2082082 | 2081025 | 2081221 | Not included | -- | -- | -- | -- | | |
| | | 2082083 | 2081025 | 2081223 | Included | -- | -- | -- | -- | | |
| Wrangler JK | 07 - 18 | 2082036 | 2081021 | 2081221 | Not included | -- | -- | -- | -- | | |
| | | 2082061 | 2081021 | 2081223 | Included | -- | -- | -- | -- | | |

Footnotes

1 - OE turn signal lamps must be relocated to the new bumper corners #2081209